



Figure 4: Thick, oversteepened road fill and slumping on Loveland Bay Road at stream crossing



Figure 5: Stream flow impounded by undersized culvert, causing ponding, on Loveland Bay Road