

**Annual Reclamation Report  
Cover Letter Summary Table**

The Annual Reclamation Report submission must be accompanied by a cover letter that includes the following data entered in the tabulated format shown below:

<b>Company:</b>	<b>Nyrstar</b>	
<b>Mine Name:</b>	<b>Myra Falls</b>	
<b>Mines Act Permit #:</b>	<b>M-26</b>	
	<b>Previous Report (e.g., 2017)</b>	<b>Current Report (e.g., 2018)</b>
<b>Total Disturbance Area (ha)</b>	<b>198.7</b>	<b>197.8</b>
<b>Total Reclaimed Area (ha)</b>	<b>22.3</b>	<b>22.3</b>
<b>Total Exempt Area (ha) (i.e., pit walls)</b>	<b>23.9</b>	<b>23.9</b>
<b>Mining Production (annual total)</b>	<b>0</b>	<b>53,231</b>
<b>Milling Production (annual total)</b>	<b>0</b>	<b>46,413</b>
<b>Total Liability Estimate</b>	<b>\$127,641,320</b>	<b>\$130,345,292</b>
<b>Date for next Five Year Mine Plan and Reclamation Plan update (if required)</b>	<b>January 31, 2021</b>	